ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0084, W0118, W0129, W0086, W0141	NA	Jakkur Layout
Segment No.	**Total Length (m)**	
7/C-W0084/S052012	399.25	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	143.37	77.599292	13.071688	77.598922	13.070449	W0118	Dead End
2	255.88	77.598562	13.072706	77.598004	13.070460	Crosss road	Jakkur lyt Main Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains in Jakkur Layout and Surrounding areas in ward no.07, Byatarayanapura	10000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1.Construction of RCC Drain.2.Providing and laying Covering slabs.	007-19-000007
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/177/18-19	29/01/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
29/01/2019	25/01/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00
Phone No.	**E-Mail ID**	
9972424626		

Field Inspection Details

Number of Trees

0

Any Other Information

Name

Pushpalatha.N.D

Date of Inspection

30/01/2019

Remarks

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	01/02/2019	28/02/2019	As proposed
SE	Basavaraj R Kabade	31/01/2019	28/02/2019	forwarded
EE	H.T.Mohandas	31/01/2019	28/02/2019	Verified
AEE	H.Ranganath	30/01/2019	28/02/2019	Verified
AE	Pushpaltha.N.D	30/01/2019	28/02/2019	Mobile Verification Done
AE	Pushpalatha.N.D	29/01/2019	28/02/2019	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0084, W0118, W0129, W0086,

Pushpalatha.N.D
AE(Civil)

Assistant Executive Engineer,
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.
Bangalore.

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0132	NA	Ashwathappa Road
Segment No.	**Total Length (m)**	
7/S-W0132/S052439	116.53	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	116.53	77.600373	13.070729	77.601424	13.070510	W0171	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains in Jakkur Layout and Surrounding areas in ward no.07, Byatarayanapura	10000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1.Providing and laying CC Road.	007-19-000007
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/177/18-19	29/01/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
29/01/2019	28/01/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00
Phone No.	**E-Mail ID**	
9972424626		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
30/01/2019		

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	01/02/2019	28/02/2019	As proposed
SE	Basavaraj R Kabade	31/01/2019	28/02/2019	forwarded
EE	H.T.Mohandas	31/01/2019	28/02/2019	Verified
AEE	H.Ranganath	30/01/2019	28/02/2019	Verified
AE	Pushpalatha.N.D	30/01/2019	28/02/2019	Mobile Verification Done
AE	Pushpalatha.N.D	29/01/2019	28/02/2019	Forwarded

Pushpalatha.N.D
AE

Assistant Executive Engineer,
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.,
Bangalore.

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0137, W0086, W0084, W0133, W0131	NA, Vinayaka Lyt 4th Crs	Jakkur Layout
Segment No.	**Total Length (m)**	
7/C-W0137/S050607	400.49	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	144.83	77.598986	13.071761	77.598620	13.070505	11th Cross	Main Road
2	91.20	77.598878	13.072738	77.598717	13.071929	10th Cross	Main Road
3	164.46	77.598695	13.071818	77.598264	13.070395	10th A Cross	Main Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains in Jakkur Layout and Surrounding areas in ward no.07, Byatarayanapura	10000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1.Construction of RCC Drain.2.Providing and laying Covering slabs.	007-19-000007
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/177/18-19	29/01/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
29/01/2019	28/01/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00
Phone No.	**E-Mail ID**	
9972424626		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
30/01/2019		

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0137, W0086, W0084, W0133,

Pushpalatha.N.D

DEE(E)

Assistant Executive Engineer,
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.,
Bangalore.

Drain Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	01/02/2019	28/02/2019	As proposed
SE	Basavaraj R Kabade	31/01/2019	28/02/2019	forwarded
EE	H.T.Mohandas	31/01/2019	28/02/2019	Verified
AEE	H.Ranganath	30/01/2019	28/02/2019	Verified
AE	Pushpalatha.N.D	30/01/2019	28/02/2019	Mobile Verification Done
AE	Pushpalatha.N.D	29/01/2019	28/02/2019	Forwarded

Pushpalatha.N.D
AE(127)

Assistant Executive Engineer.
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.,
Bangalore.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0137, W0086, W0084, W0133, W0121